

HISTORIC RESOURCE INVENTORY FORM

Resource Address: 613 N Main St Columbia Illinois 62236 USA
County: Monroe
Historic name: Sears Home
Present name:
Local place name:
Visible from public right of way:
Ownership:
Owner/Address:
Land unit size:
Site/Setting:



Lat/Long: 38.4478679999999900, -90.2046888809509200 [WGS84]

UTM: Zone 15S, 743942.9254 mE, 4259210.5924 mN

Parcel No.

Historical Information

Historic Function: Domestic: Single Dwelling	Current Function: Domestic: Single Dwelling
Construction Date: ca.	Architect: Sears, Roebuck & Company
Original or Significant Owners:	Builder:
Significant Date/Period:	Developer:
Areas of Significance:	

Architectural Information

Category: building, Single-family residence	Style:	<input type="checkbox"/> Additions <input checked="" type="checkbox"/> Alterations <input type="checkbox"/> Moved <input type="checkbox"/> Other Ancillary structures:
Structural:	Exterior Material(s): original brick, modern vinyl siding	
Stories: 1, Bays:	Roof Material: modern asphalt shingles	
Form or Plan: bungalow, rectangular	Roof Type: Medium hip , open cornice	
Foundation: raised brick	Windows: modern vinyl 6/1 double-hung sashes	
General condition: Fair	Chimney(s): one brick side right exterior	
Basement:	Porch: single-story single-bay central open porch	

Historical Summary:

One of only two known Sears kit homes in Columbia.

Status (Current Listing or Designation)

National: indiv. district landmrk.
 State/Province: indiv. district landmrk.
 Local: indiv. district landmrk.

Evaluation (Preparer's Assessment of Eligibility)

Recommendation
 Individually eligible
 Eligible as contributing resource
 Not eligible / non-contributing
 Not determined

Level of potential eligibility
 National
 State
 Local

Landmark potential
 National
 State
 Local

Description/Remarks

This is a 1-story single-family residence. The foundation is raised brick. Exterior walls are original brick and modern vinyl siding. The building has a medium hip roof clad in modern asphalt shingles with open cornice. There is one side right, exterior, brick chimney. Windows are modern vinyl, 6/1 double-hung sashes. It appears that all of the main floor windows have been replaced. There is a single-story, single-bay central open porch characterized by a hip roof clad in asphalt shingles with battered brick posts. Entrance with transom and sidelights. Covered in modern screen door. Potential Local Landmark

Survey and Recorder		
Project: City of Columbia, Illinois Historic Properties Architectural Survey	Sequence/Key no.:	Survey Date: 18 May 2013
Prepared By: Emilie Eggemeyer, Historical Foundations	Report Title/Name: Community Preservation Plan	Previous Surveys:
Inventoried: 06/24/2014 7:57:01 pm Last updated: 06/24/2014 7:57:39 pm by /	Level of Survey: <input checked="" type="checkbox"/> Reconnaissance <input type="checkbox"/> Intensive	Additional Research Recommended? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No