

HISTORIC RESOURCE INVENTORY FORM

Resource Address: 1009 Clinton St Galena Illinois 61036 USA
County: Jo Daviess
Historic name: House
Present name: House
Local place name:
Visible from public right of way: Yes
Ownership:
Owner/Address:
Land unit size:
Site/Setting:



Imported image from Ball State Survey

Lat/Long: 42.4285582900000000, -90.4326777400000000 [WGS84]

UTM: Zone , 0.0000 mE, 0.0000 mN

Parcel No. 22-101-162-00

Historical Information

Historic Function: Domestic: Single Dwelling	Current Function: Domestic: Single Dwelling
Construction Date: ca. 1870-1879 , approximate 1870*	Architect:
Original or Significant Owners:	Builder:
Significant Date/Period:	Developer:
Areas of Significance: Architecture	

Architectural Information

Category: building, domestic building	Style:	Demolished: <input type="checkbox"/> Additions <input type="checkbox"/> Alterations <input type="checkbox"/> Moved <input type="checkbox"/> Other Ancillary structures:
Structural:	Exterior Material(s): aluminum siding	
Stories: 1.5, Bays:	Roof Material: asphalt shingles	
Form or Plan: T-plan, rectangular	Roof Type: Cross gable	
Foundation: Not Visible	Windows:	
General condition: Good	Chimney(s):	
Basement:	Porch:	

Historical Summary:

Status (Current Listing or Designation)

National: indiv. district landmrk.
 State/Province: indiv. district landmrk.
 Local: indiv. district landmrk.
 Galena Historic District

Evaluation (Preparer's Assessment of Eligibility)

Recommendation
 Individually eligible
 Eligible as contributing resource
 Not eligible / non-contributing
 Not determined

Level of potential eligibility
 National
 State
 Local

Landmark potential
 National
 State
 Local



Imported image from Ball State Survey



Imported image from Ball State Survey



Imported image from Ball State Survey



Imported image from Ball State Survey

Description/Remarks

This is a 1.5-story domestic building built ca. 1870. The building is rectangular in plan. The foundation is not visible. Exterior walls are aluminum siding. The building has a cross gable roof clad in asphalt shingles. Windows are original or historic wood 1/1 fixed; double-or single hung. The porch is original or historic and contemporary, Enclosed; 1/2 length; Wood materials; Flat roof; Turned spindles. Doors are original or historic wood; glass glazed; paneled. Bay window

Survey and Recorder		
Project: Galena National Register Historic District	Sequence/Key no.:	Survey Date:
Prepared By:	Report Title/Name:	Previous Surveys:
Inventoried: 12/09/2013 8:39:30 pm Last updated: 12/09/2013 8:39:30 pm by /	Level of Survey: <input type="checkbox"/> Reconnaissance <input type="checkbox"/> Intensive	Additional Research Recommended? <input type="checkbox"/> Yes <input type="checkbox"/> No