

# HISTORIC RESOURCE INVENTORY FORM

Resource Address: <b>307 Decatur St Galena Illinois 61036 USA</b>
County: Jo Daviess
Historic name: Callahan House
Present name: HPA Site Office
Local place name:
Visible from public right of way: Yes
Ownership:
Owner/Address:
Land unit size:
Site/Setting:



Imported image from Ball State Survey

Lat/Long: 42.4101656100000000, -90.4264329500000000 [WGS84]

UTM: Zone , 0.0000 mE, 0.0000 mN

Parcel No. 06-500-171-00

## Historical Information

Historic Function: Domestic: Single Dwelling	Current Function: Commerce/Trade: Business
Construction Date: ca. 1890-1899 , 1891*	Architect:
Original or Significant Owners:	Builder:
Significant Date/Period:	Developer:
Areas of Significance: Architecture	

## Architectural Information

Category: building, domestic building	Style:	<b>Demolished:</b> <input type="checkbox"/> Additions <input type="checkbox"/> Alterations <input type="checkbox"/> Moved <input type="checkbox"/> Other Ancillary structures:
Structural:	Exterior Material(s): wood clapboard/siding	
Stories: 2, Bays:	Roof Material: wood shingles	
Form or Plan: gable front, rectangular	Roof Type: Front-gable	
Foundation: Limestone	Windows:	
General condition: Good	Chimney(s):	
Basement:	Porch:	

## Historical Summary:

### Status (Current Listing or Designation)

National:  indiv.  district  landmrk.  
 State/Province:  indiv.  district  landmrk.  
 Local:  indiv.  district  landmrk.  
 Galena Historic District

### Evaluation (Preparer's Assessment of Eligibility)

*Recommendation*  
 Individually eligible  
 Eligible as contributing resource  
 Not eligible / non-contributing  
 Not determined

*Level of potential eligibility*  
 National  
 State  
 Local

*Landmark potential*  
 National  
 State  
 Local



Imported image from Ball State Survey



Imported image from Ball State Survey



Imported image from Ball State Survey

**Description/Remarks**

This is a 2-story domestic building built in 1891. The building is rectangular in plan. The foundation is limestone. Exterior walls are wood clapboard/siding. The building has a front-gable roof clad in wood shingles. Windows are original or historic wood 1/1 double-or single hung; with molding. Doors are original or historic wood; glass glazed; paneled with transom; molding around door. Small 2-story side gable 1830s House located on property.

<b>Survey and Recorder</b>		
Project: Galena National Register Historic District	Sequence/Key no.:	Survey Date:
Prepared By:	Report Title/Name:	Previous Surveys:
Inventoried: 12/09/2013 8:39:32 pm Last updated: 12/09/2013 8:39:32 pm by /	Level of Survey: <input type="checkbox"/> Reconnaissance <input type="checkbox"/> Intensive	Additional Research Recommended? <input type="checkbox"/> Yes <input type="checkbox"/> No