

HISTORIC RESOURCE INVENTORY FORM

Resource Address: 919 S Bench St Galena Illinois 61036 USA
County: Jo Daviess
Historic name: Garage
Present name: Garage
Local place name:
Visible from public right of way: Yes
Ownership:
Owner/Address:
Land unit size:
Site/Setting:



Imported image from Ball State Survey

Lat/Long: 42.4083275000000000, -90.4335395800000000 [WGS84]

UTM: Zone 15T, 711190.3971 mE, 4698305.0223 mN

Parcel No. 22-101-355-10

Historical Information

Historic Function: Domestic: Secondary Structure	Current Function: Domestic: Secondary Structure
Construction Date: ca. 1950-1959 , approximate 1950*	Architect:
Original or Significant Owners:	Builder:
Significant Date/Period:	Developer:
Areas of Significance:	

Architectural Information

Category: building, domestic building	Style:	<input type="checkbox"/> Additions <input type="checkbox"/> Alterations <input type="checkbox"/> Moved <input type="checkbox"/> Other Ancillary structures:
Structural:	Exterior Material(s): brick	
Stories: 1, Bays:	Roof Material: Metal	
Form or Plan: , rectangular	Roof Type:	
Foundation: Concrete Block	Windows:	
General condition: Deteriorated	Chimney(s):	
Basement:	Porch:	

Historical Summary:

Status (Current Listing or Designation)

National: indiv. district landmrk.
 State/Province: indiv. district landmrk.
 Local: indiv. district landmrk.
 Galena Historic District

Evaluation (Preparer's Assessment of Eligibility)

<i>Recommendation</i>	<i>Level of potential eligibility</i>	<i>Landmark potential</i>
<input type="checkbox"/> Individually eligible	<input type="checkbox"/> National	<input type="checkbox"/> National
<input type="checkbox"/> Eligible as contributing resource	<input type="checkbox"/> State	<input type="checkbox"/> State
<input checked="" type="checkbox"/> Not eligible / non-contributing	<input type="checkbox"/> Local	<input type="checkbox"/> Local
<input type="checkbox"/> Not determined		

Description/Remarks

This is a 1-story domestic building built ca. 1950. The building is rectangular in plan. The foundation is concrete block. Exterior walls are brick. Windows are original or historic wood fixed. Doors are contemporary aluminum glazed.

Survey and Recorder

Project: Historic Resources of Galena, Illinois	Sequence/Key no.:	Survey Date:
Prepared By:	Report Title/Name:	Previous Surveys:
Inventoried: 12/09/2013 8:39:10 pm Last updated: 11/02/2019 1:27:51 am by /	Level of Survey: <input type="checkbox"/> Reconnaissance <input type="checkbox"/> Intensive	Additional Research Recommended? <input type="checkbox"/> Yes <input type="checkbox"/> No