

HISTORIC RESOURCE INVENTORY FORM

Resource Address: 608 S High St Galena Illinois 61036 USA
County: Jo Daviess
Historic name: House
Present name: House
Local place name:
Visible from public right of way: Yes
Ownership:
Owner/Address:
Land unit size:
Site/Setting:



Imported image from Ball State Survey

Lat/Long: 42.4102456900000000, -90.4350521600000000 [WGS84]

UTM: Zone , 0.0000 mE, 0.0000 mN

Parcel No. 22-100-719-00

Historical Information

Historic Function: Domestic: Single Dwelling	Current Function: Domestic: Single Dwelling
Construction Date: ca. 1900-1909 , approximate 1900*	Architect:
Original or Significant Owners:	Builder:
Significant Date/Period:	Developer:
Areas of Significance:	

Architectural Information

Category: building, domestic building	Style:	Demolished: <input type="checkbox"/> Additions <input type="checkbox"/> Alterations <input type="checkbox"/> Moved <input type="checkbox"/> Other Ancillary structures:
Structural:	Exterior Material(s): asbestos siding	
Stories: 1.5, Bays:	Roof Material: asphalt shingles	
Form or Plan: central passage, rectangular	Roof Type: Side-gable	
Foundation: Concrete Block	Windows:	
General condition: Good	Chimney(s):	
Basement:	Porch:	

Historical Summary:

Status (Current Listing or Designation)

National: indiv. district landmrk.
 State/Province: indiv. district landmrk.
 Local: indiv. district landmrk.
 Galena Historic District

Evaluation (Preparer's Assessment of Eligibility)

Recommendation

- Individually eligible
 Eligible as contributing resource
 Not eligible / non-contributing
 Not determined

Level of potential eligibility

- National
 State
 Local

Landmark potential

- National
 State
 Local



Imported image from Ball State Survey

Description/Remarks

This is a 1.5-story domestic building built ca. 1900. The foundation is concrete block. Exterior walls are asbestos siding. The building has a side-gable roof clad in asphalt shingles. Windows are original or historic; contemporary wood; vinyl 1/1; 3-light double- or single-hung; awning. The porch is contemporary, Less than Full-Height Entry; Enclosed; Asbestos siding materials; Front-Gable roof. Entrance has been enclosed as a vestibule area. Garage addition.

Survey and Recorder		
Project: Historic Resources of Galena, Illinois	Sequence/Key no.:	Survey Date:
Prepared By:	Report Title/Name:	Previous Surveys:
Inventoried: 12/10/2013 8:55:53 pm Last updated: 12/10/2013 8:55:53 pm by /	Level of Survey: <input type="checkbox"/> Reconnaissance <input type="checkbox"/> Intensive	Additional Research Recommended? <input type="checkbox"/> Yes <input type="checkbox"/> No