

HISTORIC RESOURCE INVENTORY FORM

Resource Address: 333 Wisconsin Ave Oak Park Illinois 60302 USA
County: Cook
Historic name:
Present name:
Local place name:
Visible from public right of way: Yes
Ownership:
Owner/Address:
Land unit size:
Site/Setting:



Lat/Long: 41.8820279696122200, -87.8026862539673000 [WGS84]

UTM: Zone 16T, 433400.5484 mE, 4636989.5152 mN

Parcel No.

Historical Information

Historic Function: Domestic: Single Dwelling	Current Function: Domestic: Single Dwelling
Construction Date: ca. 1880-1889 , approximate 1888*	Architect:
Original or Significant Owners:	Builder:
Significant Date/Period:	Developer:
Areas of Significance:	

Architectural Information

Category: building, Single-family residence	Style: Stick	<input checked="" type="checkbox"/> Additions <input type="checkbox"/> Alterations <input type="checkbox"/> Moved <input type="checkbox"/> Other Ancillary structures: 1 total including garage
Structural: frame	Exterior Material(s): original Wood Clapboard, original wood shingles	
Stories: 2, Bays:	Roof Material: replacement asphalt shingles	
Form or Plan: Cross Gable, rectangular	Roof Type: Cross gable	
Foundation: Stone	Windows: historic wood 1/1 double-hung sashes	
General condition:	Chimney(s):	
Basement:	Porch: single-story Full-width open porch	

Historical Summary:

House appears on 1895 Sanborn Fire Insurance map

Status (Current Listing or Designation)

National: indiv. district landmrk.
 State/Province: indiv. district landmrk.
 Local: indiv. district landmrk.
 Ridgeland/Oak Park National Register District 1983

Ridgeland/Oak Park Historic District 1994

Evaluation (Preparer's Assessment of Eligibility)

Recommendation

Individually eligible
 Eligible as contributing resource
 Not eligible / non-contributing
 Not determined

Level of potential eligibility

National
 State
 Local

Landmark potential

National
 State
 Local



Description/Remarks

This is a 2-story single-family residence in the Stick style built ca. 1888. The structural system is frame. The foundation is stone. Exterior walls are original wood clapboard and original wood shingles. Decorative wood ornament. The building has a cross gable roof clad in replacement asphalt shingles. Windows are historic wood, 1/1 double-hung sashes. There is a single-story, full-width open porch characterized by a hip roof clad in asphalt shingles with turned wood posts. Paired entry doors with transom window. There is a two-story, rear, frame addition. Residential addition, front turret added in 1990s.

Other sources: Building permit records.

Survey and Recorder		
Project: Historic Resources of Oak Park	Sequence/Key no.:	Survey Date: February 19, 2016
Prepared By: Douglas Kaarre, AICP Village of Oak Park	Report Title/Name: Survey and Planning	Previous Surveys: Second District Survey 1978
Inventoried: 02/19/2016 10:47:46 pm Last updated: 03/26/2020 12:18:13 pm by /	Level of Survey: <input type="checkbox"/> Reconnaissance <input checked="" type="checkbox"/> Intensive	Additional Research Recommended? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No