

**KENTUCKY HISTORIC PROPERTIES
SURVEY FORM 2017-01**

SHPO EVALUATION

COUNTY: Shelby County
RESOURCE NUMBER: SHS 815
EVALUATION: H / NR District Contributing N / Eligible
Member of a Group
CONDITION: E / Excellent - Fully utilized

1. NAME OF RESOURCE:

commercial building

How Determined: 10 / Type of building (house, barn, etc.)

2. ADDRESS/LOCATION:

306-308 Main St, Shelbyville, Kentucky

3. GEOGRAPHIC DATA:

Quad: Shelbyville

Date: 1993

Lat: 38.210683

Long: -85.213209

4. FIELD RECORDER/AFFILIATION:

Glen Payne, CRE Planning and Development

5. DATE RECORDED: October 2013

6. SPONSOR/INITIATION: 2 / Certified Local Govt project

Sponsor Name: City of Shelbyville

7. PREVIOUSLY RECORDED:

8. REPORT/NR REFERENCE:

Survey and Planning

9. ORIGINAL PRIMARY FUNCTION:

01A / Domestic: Single Dwelling

10. CURRENT PRIMARY FUNCTION:

02 / Commerce/Trade: Professional

11. ORIGINAL CONSTRUCTION DATE:

Estimated: 4 / 1900-1924

Documented: Field observation

12. MAJOR ADDITIONS/MODIFICATION (specify)

1935 Residential structure added at rear. 1990 Renovated

13. MODIFICATION ASSESSMENT:

2 / Moderate alteration

14. CONSTRUCTION METHOD AND MATERIAL:

Original/Primary (if known): B0 / masonry

Subsequent/Secondary (if known):

Other:

15. PRIMARY WALL MATERIAL:

Original (if known): D / Brick

Current:

16. DIMENSIONS:

Height: B / 1.5

Acreage: 0.101528941

17. ARCHITECTURAL FORM/SHAPE:

A / rectangular

18. ARCHITECTURAL TYPE (choose from applicable list(s)):

Type: O / Minimal traditional

Other:

19. ARCHITECTURAL STYLE (choose from applicable list(s)):

Style: 51 / Colonial Revival

Other:

20. FOUNDATION WALLS:

Type: 2 / Continuous

Material: B / Brick

21. ROOFING:

Configuration: A / Medium side gable

Roof Covering: 5 / Asphalt shingles

22. ARCHITECT/BUILDER (if known):

23. WINDOWS: __ Original __X_ Replacement

Current Material: W / Wood

Sash Operation: D / Double or Single Hung

Glazing Pattern: M / Multi-Light

24. NUMBER OF SUPPORT RESOURCES: 0 / None

(If yes, complete #27 and #28 below)

25. COMMENTS/HISTORICAL INFORMATION: (Complete on Continuation Sheet)

26. PHOTO: (Place Additional Photos below under 26 cont'd)



SITE PLAN KEY	NAME OF RESOURCE	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL

28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):

29: MAP (Scan or attach copy of map showing exact location of resources):

25. (continued) COMMENTS/HISTORICAL INFORMATION:

This is a 1.5-story, 4-bay commercial building in the Colonial Revival style built in the period 1910-1919. The structural system is masonry. The foundation is continuous brick. Exterior walls are original brick. The building has a medium side gable roof clad in replacement asphalt shingles with flush eaves and two gabled dormers. There is one offset left, straddle ridge, brick chimney and one offset right, straddle ridge, brick chimney. Windows are replacement wood, 12/12 double-hung sashes. There are two single-entry doorways with multi-light transom windows. There is a two-story, rear, frame addition. Residential structure added at rear. Residential structure added at rear. Renovated

27. (continued) ADDITIONAL IMAGES:



Caption: 306-308 Main detail



Caption: 306-308 Main rear view