

KENTUCKY HISTORIC PROPERTIES  
SURVEY FORM 2017-01

SHPO EVALUATION

COUNTY: Shelby County  
RESOURCE NUMBER: SHS 706  
EVALUATION: N / Eligible Member of a Group  
CONDITION: G / Good - in good state of repair

1. NAME OF RESOURCE:

domestic building

How Determined: 10 / Type of building (house, barn, etc.)

2. ADDRESS/LOCATION:

1312-1314 Main St, Shelbyville, Kentucky. FAIRVIEW SUB LOT 6

3. GEOGRAPHIC DATA:

Quad: Shelbyville

Date: 1993

Lat: 38.211813

Long: -85.231519

4. FIELD RECORDER/AFFILIATION:

Glen Payne, CRE Planning and Development

5. DATE RECORDED: October 2013

6. SPONSOR/INITIATION: 2 / Certified Local Govt project

Sponsor Name: City of Shelbyville

7. PREVIOUSLY RECORDED:

8. REPORT/NR REFERENCE:

Survey and Planning

9. ORIGINAL PRIMARY FUNCTION:

01B / Domestic: Multiple Dwelling

10. CURRENT PRIMARY FUNCTION:

01B / Domestic: Multiple Dwelling

11. ORIGINAL CONSTRUCTION DATE:

Estimated: 3 / 1925-1949

Documented: Field observation

12. MAJOR ADDITIONS/MODIFICATION (specify)

13. MODIFICATION ASSESSMENT:

1 / Little or no modification

14. CONSTRUCTION METHOD AND MATERIAL:

Original/Primary (if known): W3 / frame

Subsequent/Secondary (if known):

Other:

15. PRIMARY WALL MATERIAL:

Original (if known): C / Brick veneer

Current:

16. DIMENSIONS:

Height: C / 2

Acreage: 0.223385213

17. ARCHITECTURAL FORM/SHAPE:

A / square

18. ARCHITECTURAL TYPE (choose from applicable list(s)):

Type: O / Duplex

Other:

19. ARCHITECTURAL STYLE (choose from applicable list(s)):

Style: 65 / Craftsman

Other:

20. FOUNDATION WALLS:

Type: 2 / Continuous

Material: R / Poured concrete

21. ROOFING:

Configuration: 1 / Bellcast hip

Roof Covering: 5 / Asphalt shingles

22. ARCHITECT/BUILDER (if known):

23. WINDOWS:  Original  Replacement

Current Material: W / Wood

Sash Operation: D / Double or Single Hung

Glazing Pattern: M / Multi-Light

24. NUMBER OF SUPPORT RESOURCES: A / 1-5

(If yes, complete #27 and #28 below)

25. COMMENTS/HISTORICAL INFORMATION: (Complete on Continuation Sheet)

26. PHOTO: (Place Additional Photos below under 26 cont'd)



SITE PLAN KEY	NAME OF RESOURCE	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL

The garage is brick with a hipped roof.

**28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):**

**29: MAP (Scan or attach copy of map showing exact location of resources):**

**25. (continued) COMMENTS/HISTORICAL INFORMATION:**

This is a 2-story, 4-bay domestic building in the Craftsman style built in the period 1920-1929. The building is square in plan. The structural system is frame. The foundation is poured concrete. Exterior walls are original brick veneer. The building has a bellcast hip roof clad in replacement asphalt shingles with box cornice and modillions. The roof is characterized by deep eaves with twin modillions at regular intervals. There are two straddle ridge, brick chimneys. Windows are original wood, 10/1 double-hung sashes. Some windows are actually 14 over 1, while others are replacement aluminum 1 over 1 double hungs. There are twin single-story porches with hipped roofs at each of the east and west entries. Apart from storm doors the... doorways appear to be original divided light wood, flanked by divided sidelights.

27. (continued) ADDITIONAL IMAGES:



**Caption:** (source: JimCleveland)