

State of California - The Resources Agency  
**DEPARTMENT OF PARKS AND RECREATION**  
**PRIMARY RECORD**

Primary #: \_\_\_\_\_  
HRI #: \_\_\_\_\_  
Trinomial: \_\_\_\_\_  
CRHR Status Code: 6Z

Other Listings: \_\_\_\_\_  
Review Code \_\_\_\_\_ Reviewer \_\_\_\_\_  
Date \_\_\_\_\_

Page 1 of 2

\*Resource Name or # (Assigned by recorder) : 8715 Santa Monica Blvd

P1. Other Identifier: \_\_\_\_\_

\*P2. Location:  Not for Publication  Unrestricted

\*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

\*b. USGS 7.5' Quad: Date: T : R : of S : \_\_\_ B.M.

c. Address: 8715 Santa Monica Blvd City: West Hollywood Zip: 90069

d. UTM: (Give more than one for large and/or linear resources) Zone: 11S, 372616.0394 mE / 3772707.4221 mN

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) : Parcel # 4339-007-013

\*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a commercial building built in 1927.

\*P3b. Resource Attributes (List attributes and codes):

\*P4. Resources Present:  Building  Structure  Object  Site  Element of District  Other (Isolates, etc.)

P5a. Photograph or Drawing (Photo required for buildings, structures, and objects.)

P5b. Description of photo: (View, data, accession #)

\*P6. Date Constructed/Age and Source:

Historic  Prehistoric  Both  
1927

\*P7. Owner and Address:

\*P8. Recorded by: (Name, affiliation, and address)

GPA Consulting, 617 S. Olive Street, Suite 910, Los Angeles, CA 90014

\*P9. Date Recorded:

Date surveyed: 2016.  
Record prepared: 06/20/2016

\*P10. Survey Type: (Describe)

Intensive

\*P11. Report Citation: (Cite survey report and other sources or enter "none.")

West Hollywood Historic Resources Survey

\*Attachments:  None  Location Map  Sketch Map  Continuation Sheet  Building, Structure, and Object Record  Archeological Record  
 District Record  Linear Feature Record  Milling Station Record  Rock Art Record  Artifact Record  Photograph Record  
 Other (List): \_\_\_\_\_

**DEPARTMENT OF PARKS AND RECREATION  
BUILDING, STRUCTURE, AND OBJECT RECORD**

Primary #: \_\_\_\_\_  
HRI #: \_\_\_\_\_  
Trinomial: \_\_\_\_\_  
CRHR Status Code: 6Z

\*Resource Name or # (Assigned by recorder): 8715 Santa Monica Blvd

Page 2 of 2

B1. Historic Name:

B2. Common Name:

B3. Original Use:

B4. Present Use:

\*B5. Architectural Style:

\*B6 Construction History: (Construction date, alterations, and date of alterations)

Date: 1927

\*B7. Moved?  Yes  No

Date: Original Location:

\*B8. Related Features:

B9a. Architect:

b. Builder:

B10. Significance: Theme: Area:

Period of Significance:

Property Type: commercial building

Applicable Criteria:

(Discuss importance in terms of historical or architectural context as defined by theme, period, and geographic scope. Also address integrity.)

6Z: Found ineligible for NR, CR or Local designation through survey evaluation.

B11. Additional Resource Attributes (List attributes and codes):

\*B12. References:

B13. Remarks:

B14. Evaluator: GPA Consulting, 617 S. Olive Street, Suite 910, Los Angeles, CA 90014

\*Date of Evaluation: Date surveyed: 2016. Record prepared: 06/20/2016

(This space reserved for official comments.)

(Sketch Map with north arrow required.)