

HISTORIC RESOURCE INVENTORY FORM

Resource no. NAHRGIS 247298

Resource Address: 715 W 1st Ave Albany Georgia 31702 United States (LOT 8 SOCIETY ST S/D)
County: Dougherty
Historic name:
Present name:
Local place name:
Visible from public right of way: Yes
Ownership: Private
Owner/Address:
Land unit size:
Site/Setting:



Lat/Long: 31.5878730000000000, -84.1661130000000000 [WGS84]

UTM: Zone 16R, 768915.9888 mE, 3498241.2734 mN

Parcel No. 0000D/00002/009

Historical Information

Historic Function: Domestic: Single Dwelling	Current Function: Domestic: Single Dwelling
Construction Date: ca. 1930-1939 , approximate 1930*	Architect:
Original or Significant Owners:	Builder:
Significant Date/Period:	Developer:
Areas of Significance:	

Architectural Information

Category: building, House	Style: No Academic Style	<input type="checkbox"/> Additions <input type="checkbox"/> Alterations <input type="checkbox"/> Moved <input type="checkbox"/> Other Ancillary structures:
Structural: frame	Exterior Material(s): Drop siding	
Stories: 1, Bays:	Roof Material: asphalt shingles	
Form or Plan: bungalow, rectangular	Roof Type: Cross gable	
Foundation:	Windows: original wood 6/1 double-hung sashes	
General condition: Good	Chimney(s):	
Basement:	Porch:	

Historical Summary:

Status (Current Listing or Designation)

National: indiv. district landmrk.
 State/Province: indiv. district landmrk.
 Local: indiv. district landmrk.

Evaluation (Preparer's Assessment of Eligibility)

<i>Recommendation</i>	<i>Level of potential eligibility</i>
<input type="checkbox"/> Individually eligible	<input type="checkbox"/> National
<input type="checkbox"/> Eligible as contributing resource	<input type="checkbox"/> State
<input checked="" type="checkbox"/> Not eligible / non-contributing	<input type="checkbox"/> Local
<input type="checkbox"/> Not determined	

Landmark potential

National
 State
 Local



Description/Remarks

This is a 1-story house in the No Academic Style built ca. 1930. The building is rectangular in plan. The structural system is frame. Exterior walls are drop siding. The building has a cross gable roof clad in asphalt shingles. Windows are original wood, 6/1 double-hung sashes.

Date source: Dougherty County Tax Assessor

Survey and Recorder

Project: Historic Resources of the Rawson Circle/Park Neighborhoods	Sequence/Key no.:	Survey Date: September 2014
Prepared By: Jaime L. Destefano and Michelle K. Taylor of History, Incorporated	Report Title/Name: City of Albany Historic Resources Survey	Previous Surveys:
Inventoried: 10/23/2014 12:40:47 pm Last updated: 01/30/2015 1:55:09 pm by /	Level of Survey: <input type="checkbox"/> Reconnaissance <input checked="" type="checkbox"/> Intensive	Additional Research Recommended? <input type="checkbox"/> Yes <input type="checkbox"/> No