


HISTORIC RESOURCE INVENTORY FORM

| |
|---|
| Resource Address: 216 S Cuyler Ave Oak Park Illinois 60302 USA (Between Pleasant St and Randolph St on S Cuyler Ave) |
| County: Cook |
| Historic name: |
| Present name: |
| Local place name: |
| Visible from public right of way: Yes |
| Ownership: |
| Owner/Address: |
| Land unit size: 5,936.78 sq ft |
| Site/Setting: |



2014

Lat/Long: 41.8845213000000000, -87.7825302000000000 [WGS84]

UTM: Zone 16T, 435075.4466 mE, 4637250.8981 mN

Township/Range/Section: 39N / 13E / S8 SW

Parcel No. 16-08-307-007-0000

Historical Information

| | |
|--|---|
| Historic Function: Domestic: Single Dwelling | Current Function: Domestic: Single Dwelling |
| Construction Date: ca. 1900-1909 , approximate 1900* | Architect: |
| Original or Significant Owners: | Builder: |
| Significant Date/Period: | Developer: |
| Areas of Significance: | |

Architectural Information

| | | |
|-------------------------------------|---|---|
| Category: building, Single Dwelling | Style: Vernacular | <input type="checkbox"/> Additions <input type="checkbox"/> Alterations <input type="checkbox"/> Moved <input type="checkbox"/> Other Ancillary structures: |
| Structural: frame | Exterior Material(s): wood siding | |
| Stories: 2.5, Bays: | Roof Material: replacement asphalt shingles | |
| Form or Plan: , irregular | Roof Type: Gable , open cornice | |
| Foundation: | Windows: replacement vinyl 1/1 double-hung sashes | |
| General condition: | Chimney(s): one Wood siding side left exterior | |
| Basement: | Porch: single-story Full-width enclosed porch | |

Historical Summary:

218 S Cuyler Ave is a contributing resource within the Ridgeland-Oak Park Historic District.

Status (Current Listing or Designation)

National: indiv. district landmrk.
 State/Province: indiv. district landmrk.
 Local: indiv. district landmrk.
 Ridgeland-Oak Park Historic District
 Ridgeland-Oak Park Historic District

Evaluation (Preparer's Assessment of Eligibility)

| | | |
|--|---------------------------------------|-----------------------------------|
| <i>Recommendation</i> | <i>Level of potential eligibility</i> | <i>Landmark potential</i> |
| <input type="checkbox"/> Individually eligible | <input type="checkbox"/> National | <input type="checkbox"/> National |
| <input type="checkbox"/> Eligible as contributing resource | <input type="checkbox"/> State | <input type="checkbox"/> State |
| <input type="checkbox"/> Not eligible / non-contributing | <input type="checkbox"/> Local | <input type="checkbox"/> Local |
| <input type="checkbox"/> Not determined | | |



2014



2014



2014

Description/Remarks

This is a 2.5-story single dwelling in the Vernacular style built ca. 1900. The structural system is frame. Exterior walls are wood siding. There is a band of decorative wood shingles that runs across the front of the house. The building has a gable roof clad in replacement asphalt shingles with open cornice and one gabled dormer. There is one side left, exterior, wood siding chimney. Windows are replacement vinyl, 1/1 double-hung sashes. There is a single-story, full-width enclosed porch characterized by a hip-and-gable roof clad in asphalt shingles with covered by siding wood posts. Off-center to the right on front face of house. Stairs lead up to Primary Entryway which leads directly onto front porch.

Date source: Village of Oak Park building permit archives. Other sources: Building permit records.

Survey and Recorder

| | | |
|---|---|--|
| Project: Historic Resources of Oak Park | Sequence/Key no.: | Survey Date: |
| Prepared By: | Report Title/Name: Survey and Planning | Previous Surveys: |
| Inventoried: 05/30/2019 2:48:40 pm Last updated: 04/15/2020 12:44:56 pm by / | Level of Survey: <input type="checkbox"/> Reconnaissance <input checked="" type="checkbox"/> Intensive | Additional Research Recommended? <input type="checkbox"/> Yes <input type="checkbox"/> No |