

**KENTUCKY HISTORIC PROPERTIES
SURVEY FORM 2017-01**

SHPO EVALUATION

COUNTY: Shelby County
RESOURCE NUMBER: SHS 868
EVALUATION: D / Eligible Individually
CONDITION: E / Excellent - Fully utilized

1. NAME OF RESOURCE:

Carriage House

How Determined: 10 / Type of building (house, barn, etc.)

2. ADDRESS/LOCATION:

101 Alton Dr, Shelbyville, Kentucky

3. GEOGRAPHIC DATA:

Quad: Shelbyville

Date: 1993

Lat: 38.212569

Long: -85.228263

4. FIELD RECORDER/AFFILIATION:

Glen Payne, Fred Rogers, HDC

5. DATE RECORDED: December, 2014

6. SPONSOR/INITIATION: 2 / Certified Local Govt project

Sponsor Name: City of Shelbyville

7. PREVIOUSLY RECORDED:

8. REPORT/NR REFERENCE:

Survey and Planning

9. ORIGINAL PRIMARY FUNCTION:

01A / Domestic: Single Dwelling

10. CURRENT PRIMARY FUNCTION:

01A / Domestic: Single Dwelling

11. ORIGINAL CONSTRUCTION DATE:

Estimated: 3 / 1925-1949

Documented: Field observation

12. MAJOR ADDITIONS/MODIFICATION (specify)

13. MODIFICATION ASSESSMENT:

1 / Little or no modification

14. CONSTRUCTION METHOD AND MATERIAL:

Original/Primary (if known): W3 / frame

Subsequent/Secondary (if known):

Other:

15. PRIMARY WALL MATERIAL:

Original (if known): R / Wood shingles

Current:

16. DIMENSIONS:

Height: C / 2

Acreage:

17. ARCHITECTURAL FORM/SHAPE:

E / Other (specify) / T

18. ARCHITECTURAL TYPE (choose from applicable list(s)):

Type: O / Cape cod

Other:

19. ARCHITECTURAL STYLE (choose from applicable list(s)):

Style: 46 / Shingle Style

Other:

20. FOUNDATION WALLS:

Type: 0 / Unknown/Not Visible

Material: 0 / Unknown/Not Visible

21. ROOFING:

Configuration: D / Cross gable

Roof Covering: 5 / Asphalt shingles

22. ARCHITECT/BUILDER (if known):

23. WINDOWS: Original Replacement

Current Material: W / Wood

Sash Operation: D / Double or Single Hung

Glazing Pattern: M / Multi-Light

24. NUMBER OF SUPPORT RESOURCES: A / 1-5

(If yes, complete #27 and #28 below)

25. COMMENTS/HISTORICAL INFORMATION: (Complete on Continuation Sheet)

26. PHOTO: (Place Additional Photos below under 26 cont'd)



SITE PLAN KEY	NAME OF RESOURCE	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL

28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):

COUNTY: Shelby County
RESOURCE NUMBER: SHS 868

KENTUCKY HISTORIC PROPERTIES SURVEY
CONTINUATION SHEET (2017-1)
PAGE 3

29: MAP (Scan or attach copy of map showing exact location of resources):

25. (continued) COMMENTS/HISTORICAL INFORMATION:

This is a 2-story residential building in the Shingle Style built in the period 1920-1929. The building is t in plan. The structural system is frame. The foundation is undetermined. Exterior walls are original wood shingles. The building has a cross gable roof clad in replacement asphalt shingles and one gabled dormer. There is a side gable brick chimney. Windows are original wood, 6/6 double-hung sashes. There is a side porch that is screened in.

27. (continued) ADDITIONAL IMAGES:



Caption:



Caption:



Caption:



Caption: