

KENTUCKY HISTORIC PROPERTIES
SURVEY FORM 2017-01

SHPO EVALUATION

COUNTY: Shelby County
RESOURCE NUMBER: SHS 683
EVALUATION: U / Insufficient information
CONDITION: D / Demolished - Entire site

1. NAME OF RESOURCE:

** Slated for Demolition

How Determined: 10 / Type of building (house, barn, etc.)

2. ADDRESS/LOCATION:

402 3rd St, Shelbyville, Kentucky

3. GEOGRAPHIC DATA:

Quad: _____ Date: _____
Lat: 38.211318 Long: -85.212883

4. FIELD RECORDER/AFFILIATION:

Glen Payne, Fred J. Rogers Historic District Coordinator

5. DATE RECORDED: 8-14-2012

6. SPONSOR/INITIATION: 2 / Certified Local Govt project

Sponsor Name: City of Shelbyville

7. PREVIOUSLY RECORDED:

Historic District

8. REPORT/NR REFERENCE:

Update Records

9. ORIGINAL PRIMARY FUNCTION:

01A / Domestic: Single Dwelling

10. CURRENT PRIMARY FUNCTION:

01A / Domestic: Single Dwelling

11. ORIGINAL CONSTRUCTION DATE:

Estimated: 4 / 1900-1924
Documented: Field observation

12. MAJOR ADDITIONS/MODIFICATION (specify)

13. MODIFICATION ASSESSMENT:

2 / Moderate alteration

14. CONSTRUCTION METHOD AND MATERIAL:

Original/Primary (if known): W3 / frame
Subsequent/Secondary (if known):
Other:

15. PRIMARY WALL MATERIAL:

Original (if known): 1 / Weatherboard
Current:

16. DIMENSIONS:

Height: D / 2.5 Acreage:

17. ARCHITECTURAL FORM/SHAPE:

A / rectangular

18. ARCHITECTURAL TYPE (choose from applicable list(s)):

Type: M / Irregular/asymmetrical-plan
Other:

19. ARCHITECTURAL STYLE (choose from applicable list(s)):

Style:
Other:

20. FOUNDATION WALLS:

Type: 2 / Continuous
Material: S / Stone

21. ROOFING:

Configuration: 1 / Medium hip
Roof Covering: 5 / Asphalt shingles

22. ARCHITECT/BUILDER (if known):

23. WINDOWS: __ Original __X_ Replacement

Current Material: V / Vinyl
Sash Operation: D / Double or Single Hung
Glazing Pattern: S / Single Light

24. NUMBER OF SUPPORT RESOURCES: 0 / None

(If yes, complete #27 and #28 below)

25. COMMENTS/HISTORICAL INFORMATION: (Complete on Continuation Sheet)

26. PHOTO: (Place Additional Photos below under 26 cont'd)



SITE PLAN KEY	NAME OF RESOURCE	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL

28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):

29: MAP (Scan or attach copy of map showing exact location of resources):

25. (continued) COMMENTS/HISTORICAL INFORMATION:

This is a 2.5-story, multiple-bay domestic building built in the period 1900-1909. The building is rectangular in plan. The structural system is frame. The foundation is raised stone. Exterior walls are original weatherboard. The building has a medium hip roof clad in replacement asphalt shingles with box cornice and one gabled dormer. There is one center, brick chimney. Windows are replacement vinyl, 1/1 double-hung sashes. There is a single-story, single-bay porch characterized by a flat roof clad in asphalt shingles with square wood posts.

27. (continued) ADDITIONAL IMAGES:



Caption: Side elevation facing NW



Caption: Detail of wall and foundation material



Caption: View of deterioration



Caption: Environs view facing south