KENTUCKY HISTORIC PROPERTIES SURVEY FORM 2017-01

SHPO EVALUATION

COUNTY: Shelby County
RESOURCE NUMBER: SHS 683
EVALUATION: H / NR District Contributing N / Eligible

CONDITION: Member of a Group

D / Demolished - Entire site

1. NAME OF RESOURCE:

Slated for Demolition

How Determined: 10 / Type of building (house, barn, etc.)

2. ADDRESS/LOCATION:

401 3rd St, Shelbyville, Kentucky

3. GEOGRAPHIC DATA:

Quad: Date:

Lat: 38.211392 Long: -85.212593

4. FIELD RECORDER/AFFILIATION:

Glen Payne,

5. DATE RECORDED: November 2012

6. SPONSOR/INITIATION: 2 / Certified Local Govt project

Sponsor Name: City of Shelbyville

7. PREVIOUSLY RECORDED:

8. REPORT/NR REFERENCE:

Update Records

9. ORIGINAL PRIMARY FUNCTION:

01A / Domestic: Single Dwelling

10. CURRENT PRIMARY FUNCTION:

01A / Domestic: Single Dwelling

11. ORIGINAL CONSTRUCTION DATE:

Estimated: 4 / 1900-1924

Documented: Field observation

12. MAJOR ADDITIONS/MODIFICATION (specify)

13. MODIFICATION ASSESSMENT:

1 / Little or no modification

14. CONSTRUCTION METHOD AND MATERIAL:

Original/Primary (if known): W3 / frame Subsequent/Secondary (if known):

Other:

15. PRIMARY WALL MATERIAL:

Original (if known): I / Weatherboard

Current:

16. DIMENSIONS:

Height: C / 2 Acreage:

17. ARCHITECTURAL FORM/SHAPE:

A / square

18. ARCHITECTURAL TYPE (choose from applicable list(s)):

Type: O / Four-over-four

Other:

19. ARCHITECTURAL STYLE (choose from applicable list(s)):

Style: Other:

20. FOUNDATION WALLS:

Type: 2 / Continuous

Material: R / Poured concrete

21. ROOFING:

Configuration: L / Pyramidal
Roof Covering: 5 / Asphalt shingles

22. ARCHITECT/BUILDER (if known):

23. WINDOWS: _X_ Original __ Replacement

Current Material: W / Wood

Sash Operation: D / Double or Single Hung

Glazing Pattern: S / Single Light

24. NUMBER OF SUPPORT RESOURCES: 0 / None

(If yes, complete #27 and #28 below)

 $\textbf{25. COMMENTS/HISTORICAL INFORMATION:} \ (\textbf{Complete on Continuation}$

Sheet)

26. PHOTO: (Place Additional Photos below under 26 cont'd)



COUNTY: Shelby County **RESOURCE NUMBER:** SHS 683

KENTUCKY HISTORIC PROPERTIES SURVEY

CONTINUATION SHEET (2017-1)

PAGE 2

SITE PLAN KEY	NAME OF RESOURCE	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL

28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):

COUNTY: Shelby County	KENTUCKY HISTORIC PROPERTIES SURVEY
RESOURCE NUMBER: SHS 683	CONTINUATION SHEET (2017-1) PAGE 3
	./,625
29: MAP (Scan or attach copy of map showing exact location of resources):	
25. (continued) COMMENTS/HISTORICAL INFORMATION:	
This is a 2-story, multiple-bay domestic building built in the period 1900-1909. The structural soriginal weatherboard. The building has a pyramidal roof clad in replacement asphalt shingles one offset left, side slope, brick chimney. Windows are original wood, 1/1 double-hung sashes	s with box cornice. There is one side right, exterior, brick chimney and

PAGE 4

27. (continued) ADDITIONAL IMAGES:

RESOURCE NUMBER: SHS 683

COUNTY: Shelby County





Caption: (source: Jim Cleveland)

Caption: (source: Jim Cleveland)