

**KENTUCKY HISTORIC PROPERTIES
SURVEY FORM 2017-01**

SHPO EVALUATION

COUNTY: Shelby County
RESOURCE NUMBER: SHS 566
EVALUATION: H / NR District Contributing N / Eligible
Member of a Group
CONDITION: G / Good - in good state of repair

1. NAME OF RESOURCE:

domestic building

How Determined: 10 / Type of building (house, barn, etc.)

2. ADDRESS/LOCATION:

406 8th St, Shelbyville, Kentucky. Block Number 7

3. GEOGRAPHIC DATA:

Quad: Shelbyville

Date: 1990

Lat: 38.211725

Long: -85.220512

4. FIELD RECORDER/AFFILIATION:

Glen Payne, CRE Planning

5. DATE RECORDED: October 2013

6. SPONSOR/INITIATION: 2 / Certified Local Govt project

Sponsor Name: City of Shelbyville

7. PREVIOUSLY RECORDED:

Shelbyville Historic District

8. REPORT/NR REFERENCE:

Update Records

9. ORIGINAL PRIMARY FUNCTION:

01A / Domestic: Single Dwelling

10. CURRENT PRIMARY FUNCTION:

01A / Domestic: Single Dwelling

11. ORIGINAL CONSTRUCTION DATE:

Estimated: 4 / 1900-1924

Documented: Field observation

12. MAJOR ADDITIONS/MODIFICATION (specify)

13. MODIFICATION ASSESSMENT:

2 / Moderate alteration

14. CONSTRUCTION METHOD AND MATERIAL:

Original/Primary (if known): W3 / frame

Subsequent/Secondary (if known):

Other:

15. PRIMARY WALL MATERIAL:

Original (if known): 1 / Weatherboard

Current:

16. DIMENSIONS:

Height: C / 2

Acreage: 0.174636564

17. ARCHITECTURAL FORM/SHAPE:

B / irregular

18. ARCHITECTURAL TYPE (choose from applicable list(s)):

Type: O / Queen anne

Other:

19. ARCHITECTURAL STYLE (choose from applicable list(s)):

Style:

Other:

20. FOUNDATION WALLS:

Type: 2 / Continuous

Material: S / Stone

21. ROOFING:

Configuration: D / Multi-plane cross gable

Roof Covering: 5 / Asphalt shingles

22. ARCHITECT/BUILDER (if known):

23. WINDOWS: Original Replacement

Current Material: W / Wood

Sash Operation: D / Double or Single Hung

Glazing Pattern: S / Single Light

24. NUMBER OF SUPPORT RESOURCES: 0 / None

(If yes, complete #27 and #28 below)

25. COMMENTS/HISTORICAL INFORMATION: (Complete on Continuation Sheet)

26. PHOTO: (Place Additional Photos below under 26 cont'd)



SITE PLAN KEY	NAME OF RESOURCE	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL

28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):

29: MAP (Scan or attach copy of map showing exact location of resources):

25. (continued) COMMENTS/HISTORICAL INFORMATION:

This is a 2-story, multiple-bay domestic building built in the period 1900-1909. The building is irregular in plan. The structural system is frame. The foundation is stone. Exterior walls are original weatherboard. The building has a multi-plane cross gable roof clad in replacement asphalt shingles with flush eaves. There is an internal brick chimney. Windows are original wood, 1/1 double-hung sashes. There is a single-story, single-bay porch characterized by a shed roof clad in asphalt shingles with round wood posts.

27. (continued) ADDITIONAL IMAGES:



Caption: (source: Jim Cleveland)