

KENTUCKY HISTORIC PROPERTIES
SURVEY FORM 2017-01

SHPO EVALUATION

COUNTY: Shelby County
RESOURCE NUMBER: SHS 749
EVALUATION: S / Ineligible
CONDITION: F / Fair - undermaintained

1. NAME OF RESOURCE:

commercial building

How Determined: 10 / Type of building (house, barn, etc.)

2. ADDRESS/LOCATION:

711 Main St, Shelbyville, Kentucky

3. GEOGRAPHIC DATA:

Quad: Shelbyville

Date: 1993

Lat: 38.211314

Long: -85.219334

4. FIELD RECORDER/AFFILIATION:

Glen Payne, CRE Planning

5. DATE RECORDED: October 2013

6. SPONSOR/INITIATION: 2 / Certified Local Govt project

Sponsor Name: City of Shelbyville

7. PREVIOUSLY RECORDED:

8. REPORT/NR REFERENCE:

Survey and Planning

9. ORIGINAL PRIMARY FUNCTION:

02E / Commerce/Trade: Specialty Store

10. CURRENT PRIMARY FUNCTION:

01B / Domestic: Multiple Dwelling

11. ORIGINAL CONSTRUCTION DATE:

Estimated: 4 / 1900-1924

Documented: Field observation

12. MAJOR ADDITIONS/MODIFICATION (specify)

1960

13. MODIFICATION ASSESSMENT:

14. CONSTRUCTION METHOD AND MATERIAL:

Original/Primary (if known): B0 / masonry

Subsequent/Secondary (if known):

Other:

15. PRIMARY WALL MATERIAL:

Original (if known):

Current: M / Stucco

16. DIMENSIONS:

Height: C / 2

Acreage: 0.141057926

17. ARCHITECTURAL FORM/SHAPE:

B / irregular

18. ARCHITECTURAL TYPE (choose from applicable list(s)):

Type: O / Apartment/multi-unit complex

Other:

19. ARCHITECTURAL STYLE (choose from applicable list(s)):

Style:

Other:

20. FOUNDATION WALLS:

Type: 0 / Unknown/Not Visible

Material: 0 / Unknown/Not Visible

21. ROOFING:

Configuration:

Roof Covering:

22. ARCHITECT/BUILDER (if known):

23. WINDOWS: Original Replacement

Current Material: W / Wood

Sash Operation: D / Double or Single Hung

Glazing Pattern: M / Multi-Light

24. NUMBER OF SUPPORT RESOURCES: 0 / None

(If yes, complete #27 and #28 below)

25. COMMENTS/HISTORICAL INFORMATION: (Complete on Continuation Sheet)

26. PHOTO: (Place Additional Photos below under 26 cont'd)



SITE PLAN KEY	NAME OF RESOURCE	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL

28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):

29: MAP (Scan or attach copy of map showing exact location of resources):

25. (continued) COMMENTS/HISTORICAL INFORMATION:

This is a 2-story, multiple-bay commercial building built in the period 1910-1919. The building is irregular in plan. The structural system is masonry. The foundation is undetermined. Exterior walls are replacement stucco. The roof on the commercial Main Street section is flat while the connected residential structure has a low hip roof clad in modern asphalt shingles. There is one offset left, side slope, brick chimney. Windows are original wood, 4/1 double-hung sashes. The commercial section has fixed, wooden divided and single-light windows in a storefront configuration. This is a house connected to a commercial Main Street building and as such is difficult to evaluate as a single resource.

27. (continued) ADDITIONAL IMAGES:



Caption: (Source: Jim Cleveland)