

KENTUCKY HISTORIC PROPERTIES
SURVEY FORM 2017-01

SHPO EVALUATION

COUNTY: Shelby County
RESOURCE NUMBER: SHS-520
EVALUATION: _____
CONDITION: G / Good - in good state of repair

1. NAME OF RESOURCE:

domestic building

How Determined: 10 / Type of building (house, barn, etc.)

2. ADDRESS/LOCATION:

636-638 10th St, Shelbyville, Kentucky. Block 30

3. GEOGRAPHIC DATA:

Quad: Shelbyville

Date: 1990

Lat: 38.209354

Long: -85.223948

4. FIELD RECORDER/AFFILIATION:

Glen Payne, CRE Planning, LLC

5. DATE RECORDED: October 2013

6. SPONSOR/INITIATION: 2 / Certified Local Govt project

Sponsor Name: City of Shelbyville

7. PREVIOUSLY RECORDED:

8. REPORT/NR REFERENCE:

Update Records

9. ORIGINAL PRIMARY FUNCTION:

01B / Domestic: Multiple Dwelling

10. CURRENT PRIMARY FUNCTION:

01B / Domestic: Multiple Dwelling

11. ORIGINAL CONSTRUCTION DATE:

Estimated: 3 / 1925-1949

Documented: Field observation

12. MAJOR ADDITIONS/MODIFICATION (specify)

13. MODIFICATION ASSESSMENT:

14. CONSTRUCTION METHOD AND MATERIAL:

Original/Primary (if known): W3 / frame

Subsequent/Secondary (if known):

Other:

15. PRIMARY WALL MATERIAL:

Original (if known): C / Brick veneer

Current:

16. DIMENSIONS:

Height: A / 1

Acreage: 0.222043751

17. ARCHITECTURAL FORM/SHAPE:

A / square

18. ARCHITECTURAL TYPE (choose from applicable list(s)):

Type: O / Duplex

Other:

19. ARCHITECTURAL STYLE (choose from applicable list(s)):

Style:

Other:

20. FOUNDATION WALLS:

Type: 0 / Unknown/Not Visible

Material: 0 / Unknown/Not Visible

21. ROOFING:

Configuration: 1 / Low hip

Roof Covering: 5 / Asphalt shingles

22. ARCHITECT/BUILDER (if known):

23. WINDOWS: Original Replacement

Current Material: W / Wood

Sash Operation:

Glazing Pattern: M / Multi-Light

24. NUMBER OF SUPPORT RESOURCES: 0 / None

(If yes, complete #27 and #28 below)

25. COMMENTS/HISTORICAL INFORMATION: (Complete on Continuation Sheet)

26. PHOTO: (Place Additional Photos below under 26 cont'd)



SITE PLAN KEY	NAME OF RESOURCE	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL

28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):

COUNTY: Shelby County
RESOURCE NUMBER: SHS-520

KENTUCKY HISTORIC PROPERTIES SURVEY
CONTINUATION SHEET (2017-1)
PAGE 3

29: MAP (Scan or attach copy of map showing exact location of resources):

25. (continued) COMMENTS/HISTORICAL INFORMATION:

This is a 1-story domestic building built in the period 1940-1949. The building is square in plan. The structural system is frame. The foundation is undetermined. Exterior walls are original brick veneer. The building has a low hip roof clad in replacement asphalt shingles with flush eaves. There is an internal brick chimney flue. The windows are a combination of different styles. The entryways to each portion of the duplex are characterized by enclosed porches.