

**KENTUCKY HISTORIC PROPERTIES  
SURVEY FORM 2017-01**

**SHPO EVALUATION**

COUNTY: Shelby County  
RESOURCE NUMBER: SHS 588  
EVALUATION: H / NR District Contributing  
CONDITION: E / Excellent - Fully utilized

**1. NAME OF RESOURCE:**

domestic building

**How Determined:** 10 / Type of building (house, barn, etc.)

**2. ADDRESS/LOCATION:**

903 Bland Ave, Shelbyville, Kentucky. Block 4

**3. GEOGRAPHIC DATA:**

**Quad:** Shelbyville

**Date:** 1990

**Lat:** 38.209300

**Long:** -85.222356

**4. FIELD RECORDER/AFFILIATION:**

Glen Payne, CRE Planning, LLC

**5. DATE RECORDED:** November, 2013

**6. SPONSOR/INITIATION:** 2 / Certified Local Govt project

**Sponsor Name:** City of Shelbyville

**7. PREVIOUSLY RECORDED:**

1985 Shelbyville Historic District

**8. REPORT/NR REFERENCE:**

Update Records

**9. ORIGINAL PRIMARY FUNCTION:**

01A / Domestic: Single Dwelling

**10. CURRENT PRIMARY FUNCTION:**

01A / Domestic: Single Dwelling

**11. ORIGINAL CONSTRUCTION DATE:**

**Estimated:** 4 / 1900-1924

**Documented:** Field observation

**12. MAJOR ADDITIONS/MODIFICATION (specify)**

**13. MODIFICATION ASSESSMENT:**

1 / Little or no modification

**14. CONSTRUCTION METHOD AND MATERIAL:**

**Original/Primary (if known):** W3 / frame

**Subsequent/Secondary (if known):**

**Other:**

**15. PRIMARY WALL MATERIAL:**

**Original (if known):** 1 / Weatherboard

**Current:**

**16. DIMENSIONS:**

**Height:** A / 1

**Acreage:** 0.233818474

**17. ARCHITECTURAL FORM/SHAPE:**

B / irregular

**18. ARCHITECTURAL TYPE (choose from applicable list(s)):**

**Type:** 0 / Queen anne cottage

**Other:**

**19. ARCHITECTURAL STYLE (choose from applicable list(s)):**

**Style:** 45 / Queen Anne

**Other:**

**20. FOUNDATION WALLS:**

**Type:** 2 / Continuous

**Material:**

**21. ROOFING:**

**Configuration:** S / Other (specify) / Multi-plane/complex

**Roof Covering:** 5 / Asphalt shingles

**22. ARCHITECT/BUILDER (if known):**

**23. WINDOWS:**  Original  Replacement

**Current Material:** W / Wood

**Sash Operation:** D / Double or Single Hung

**Glazing Pattern:** S / Single Light

**24. NUMBER OF SUPPORT RESOURCES:** 0 / None

(If yes, complete #27 and #28 below)

**25. COMMENTS/HISTORICAL INFORMATION:** (Complete on Continuation Sheet)

**26. PHOTO:** (Place Additional Photos below under 26 cont'd)



SITE PLAN KEY	NAME OF RESOURCE	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL

28. SITE PLAN (Complete if #24 was answered or if you are using sub-numbers):

**29: MAP (Scan or attach copy of map showing exact location of resources):**

**25. (continued) COMMENTS/HISTORICAL INFORMATION:**

This is a 1-story, multiple-bay domestic building in the Queen Anne style built in the period 1900-1909. The structural system is frame. Exterior walls are original weatherboard. The building has a multi-plane/complex roof clad in replacement asphalt shingles. There are two internal brick chimneys. Windows are original wood, 1/1 double-hung sashes. There is a wrap around front porch element.